Full Reserve Study Amelia Walk CDD No Streets Fernandina Beach, Florida



Prepared for FY 2020 Report Date: June 4, 2020





June 4, 2020

Mr. Daniel Laughlin, District Manager Governmental Management Services 475 West Town Place, Suite 114 St. Augustine Florida 32092

Re: Reserve Study Report for Amelia Walk CDD No Streets

Dear Mr. Laughlin:

Community Advisors is pleased to provide this Reserve Study report for the above referenced District. A site visit was conducted to determine the condition of your major components and provide an opinion of their remaining useful life.

We have developed a plan to fund future capital component replacements which is dependent on adequate funding, component maintenance, usage, weather and other factors. Component replacement cost is determined using local vendors and industry standard publications. This Reserve Study was prepared under the guidelines of the National Reserve Study Standards which is administrated by CAI and the Standards of Practice establish by APRA. Once you have reviewed this report and considered recent expenditures and any historic cost data, we will make necessary adjustments

Respectively submitted,

CRShamand

Charles R. Sheppard RS PRA CCI

Professional Reserve Analyst

10459 Hunters Creek Court Jacksonville, FL 32256 (904) 303-3275

www.communityadvisors.comm









TABLE OF CONTENTS

EXECUTIVE SUMMARY	
Executive Summary	1-1
Current Funding Projection	1-2
Current Funding Projection vs Fully Funded Plan	1-3
FUNDING PLAN	
Threshold Funded Plan	2-1
Recommended Funding Plan Chart	2-2
CASH FLOW	
Income & Expense Spreadsheet	3-1
EXPENDITURE DETAIL	
Annual Expenditure Detail	4-1
Asset Current Cost by Category	4-6
COMPONENT INVENTORY	
Condition Assessment	5-1
Component Inventory	5-3
Component Detail Index	5-6
Component Detail	5-9
DISCLOSURERS & INFORMATION	
Methodology & Information	6-1
Terms of Service	6-2
Definitions	6-3

Amelia Walk CDD No Streets

Fernandina Beach, Florida

Executive Summary

Report Date	June 4, 2020	
Account Number	1590	
Version	1	
Budget Year Beginning	October 1, 2020	
Budget Year Ending S	eptember 30, 2021	
Total Units	749	

Report Parameters	
Inflation	2.50%
Annual Assessment Increase	3.00%
Interest Rate on Reserve Deposit	2.00%
2020 Beginning Balance	\$50,000

ROPERTY INFORMATION

• Date of Completion: January 1, 2008

• Date of site visit: April 2, 2020

• Components Included: 29

• Current replacement cost: \$557,819

FINANCIAL INFORMATION

Level of Service: Level I Full Reserve Study

• Funding Method: The Cash Flow Method

• Funding Goal: Adequate funding with moderate contributions

• Percent Funded Beginning of Year: 21%

• Balance Required to Begin Year One Fully Funded: \$233,119


- Full Funding Contribution for Year One: Deficit of \$183,119 + Annual Contribution of \$31,263 = \$214,382 for FY 2020-2021
- Current Funding Projection: Contribution: \$100,000 for year one with annual increases of 3%. Projection on page 1-2.
- Recommend Funding Contribution: \$39,158 for year one provides adequate funding with lower contributions in subsequent years. Projection found on page 1-4.

Threshold Funding Model Summary of Calculations Required Annual Contribution \$39,157.92 \$52.28 per unit annually Average Net Annual Interest Earned \$1,475.16 Total Annual Allocation to Reserves \$40,633.07 \$54.25 per unit annually

Amelia Walk CDD No Streets Current Funding Projection

Beginning Balance: \$50,000

					Projected	Fully	
	Current	Annual	Annual	Annual	Ending	Funded	Percent
Year	Cost	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
20-21	557,819	100,000	4,038	15,400	138,638	250,777	55%
21-22	571,765	103,000	7,249		248,887	285,351	87%
22-23	586,059	106,090	10,431	7,270	358,138	314,045	114%
23-24	600,710	109,273	13,697	10,854	470,254	341,403	138%
24-25	615,728	112,551	17,484		600,289	381,335	157%
25-26	631,121	115,927	21,486		737,703	423,051	174%
26-27	646,899	119,405	25,428	9,509	873,026	456,867	191%
27-28	663,072	122,987	25,617	142,119	879,511	357,241	246%
28-29	679,649	126,677	30,186		1,036,374	401,661	258%
29-30	696,640	130,477	35,006		1,201,857	448,080	268%
30-31	714,056	134,392	37,232	95,178	1,278,303	399,010	320%
31-32	731,907	138,423	42,502		1,459,228	447,204	326%
32-33	750,205	142,576	46,334	57,346	1,590,792	438,778	363%
33-34	768,960	146,853	51,457	22,404	1,766,699	466,937	378%
34-35	788,184	151,259	57,191	11,586	1,963,562	507,892	387%
35-36	807,889	155,797	62,775	26,857	2,155,277	535,246	403%
36-37	828,086	160,471	69,472		2,385,220	591,868	403%
37-38	848,788	165,285	71,103	180,396	2,441,212	466,080	524%
38-39	870,008	170,243	76,346	66,597	2,621,204	454,900	576%
39-40	891,758	175,351	83,897		2,880,451	512,837	562%
40-41	914,052	180,611	91,832		3,152,894	573,388	550%
41-42	936,903	186,029	100,168		3,439,091	636,645	540%
42-43	960,326	191,610	97,971	365,004	3,363,668	328,578	1024%
43-44	984,334	197,359	105,881	31,675	3,635,232	355,725	1022%
44-45	1,008,942	203,279	113,773	46,084	3,906,201	370,067	1056%
45-46	1,034,166	209,378	123,467		4,239,046	433,320	978%
46-47	1,060,020	215,659	133,641		4,588,346	499,504	919%
47-48	1,086,521	222,129	139,665	154,967	4,795,173	409,886	1170%
48-49	1,113,684	228,793	149,171	51,613	5,121,523	425,383	1204%
49-50	1,141,526	235,657	160,715		5,517,895	495,626	1113%




This chart illustrates the current funding plan performance.

Amelia Walk CDD No Streets Threshold Funded Plan

Beginning Balance: \$50,000

_					Projected	Fully	
	Current	Annual	Annual	Annual	Ending	Funded	Percent
Year	Cost	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
20-21	557,819	39,158	1,475	15,400	75,233	250,777	30%
21-22	571,765	30,034	2,105		107,373	285,351	38%
22-23	586,059	30,935	2,621	7,270	133,658	314,045	43%
23-24	600,710	31,863	3,093	10,854	157,761	341,403	46%
24-25	615,728	32,819	3,812		194,392	381,335	51%
25-26	631,121	33,804	4,564		232,759	423,051	55%
26-27	646,899	34,818	5,161	9,509	263,229	456,867	58%
27-28	663,072	35,862	3,139	142,119	160,111	357,241	45%
28-29	679,649	36,938	3,941		200,990	401,661	50%
29-30	696,640	38,046	4,781		243,817	448,080	54%
30-31	714,056	39,188	3,757	95,178	191,584	399,010	48%
31-32	731,907	40,363	4,639		236,586	447,204	53%
32-33	750,205	41,574	4,416	57,346	225,231	438,778	51%
33-34	768,960	42,821	4,913	22,404	250,561	466,937	54%
34-35	788,184	44,106	5,662	11,586	288,743	507,892	57%
35-36	807,889	45,429	6,146	26,857	313,461	535,246	59%
36-37	828,086	46,792	7,205		367,458	591,868	62%
37-38	848,788	48,196	4,705	180,396	239,963	466,080	51%
38-39	870,008	49,642	4,460	66,597	227,468	454,900	50%
39-40	891,758	51,131	5,572		284,171	512,837	55%
40-41	914,052	52,665	6,737		343,573	573,388	60%
41-42	936,903	54,245	7,956		405,774	636,645	64%
42-43	960,326	55,872	1,933	365,004	98,575	328,578	30%
43-44	984,334	57,548	2,489	31,675	126,938	355,725	36%
44-45	1,008,942	59,275	2,803	46,084	142,931	370,067	39%
45-46	1,034,166	61,053	4,080		208,064	433,320	48%
46-47	1,060,020	62,885	5,419		276,368	499,504	55%
47-48	1,086,521	64,771	3,723	154,967	189,895	409,886	46%
48-49	1,113,684	66,714	4,100	51,613	209,096	425,383	49%
49-50	1,141,526	68,716	5,556		283,368	495,626	57%



This chart shows the recommended funding plan annual balances, annual expenditures and assessments.

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Beginning Balance Annual Assessment Interest Earned	50,000 39,158 1,475	75,233 30,034 2,105	107,373 30,935 2,621	133,658 31,863 3,093	157,761 32,819 3,812	194,392 33,804 4,564	232,759 34,818 5,161	263,229 35,862 3,139	160,111 36,938 3,941	200,990 38,046 4,781
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	15,400 250,777 30% 75,233	285,351 38% 107,373	7,270 314,045 43% 133,658	10,854 341,403 46% 157,761	381,335 51% 194,392	423,051 55% 232,759	9,509 456,867 58% 263,229	142,119 357,241 45% 160,111	401,661 50% 200,990	448,080 54% 243,817
Description Misc. Site Components Street Signs/Poles Wood Bulkhead - Retention Pond Wood Pergola Entry Feature Repair/Replace Wood Pilings 50%/Stringers/Deck - Pier Misc. Site Components Total:										
Fencing & Gates Aluminum Fence - Pool Aluminum Railing - Rear Patio/Ramp Chain Link Coated Fence 10 Ft - Tennis Courts Vinyl Ranch Fence - Entry Fencing & Gates Total:										
Site Lighting Decorative Light Poles - Pool Decorative Light Poles - Site Wall Laterns - Entry Feature Site Lighting Total:										
Misc. Building Components Restroom Refurbish Allowance - Club Room Restroom Refurbish Allowance - Pool/Fitness Wood Cabinets/Stone Top - Kitchen Wood Decking - Covered Porch Misc. Building Components Total:								17,117 41,010 58,127		

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Description										
Roofing										
Asphalt Shingles (Arch) - Clubhouse								36,445		
Standing Seam Metal Panels - Clubhouse										
Roofing Total:								36,445		
Exterior Painting										
Clubhouse							9,509			
Exterior Painting Total:							9,509			
Furniture Fixtures & Equipment										
Furniture Allowance - Club Room										
Furniture Allowance - Patio/Deck										
Furniture Allowance - Pool Deck										
Shade Structure Fabric			7,270							
Furniture Fixtures & Equipment Total:			7,270							
HVAC										
Heat Pump 5 Ton	7,000									
Heat Pump 6 Ton	8,400									
HVAC Total:	15,400									
Swimming Pool										
Concrete Pavers/Pool Deck/Patio										
Filtration Refurbishment Allowance										
Pool Resurfacing/Tile										
Swimming Pool Total:										
Tennis Courts										
Asphalt Resurfacing (Color Coat)				10,854						
Tennis Courts Total:				10,854						
Playground										
Play Equipment Allowance								47,547		
Playground Total:								47,547		

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Description										
Components Not Included										
Access Controller/Devices - Amenity	Unfunded									
Aluminum Gutters/DS - Clubhouse	Unfunded									
Asphalt Seal Coat - Parking Lot	Unfunded									
Asphalt Shingles (Arch) - Pier Pavilion	Unfunded									
Asphalt Shingles (Arch) - Tennis Pavilion	Unfunded									
Backstop - Tennis Courts	Unfunded									
Brick Wall Cleaning/Repair/Replace	Unfunded									
Carpet - Office/Storage	Unfunded									
Catch Basin Repair	Unfunded									
Concrete Curb/Walk Allowance - Parking Lot	Unfunded									
Concrete Pavers Majestic Walk Blvd.	Unfunded									
Drainage Structures/Pipe	Unfunded									
Entry Feature	Unfunded									
Fitness Equipment (Partial Replacement)	Unfunded									
Fitness Equipment Allowance (Full Replacemen	Unfunded									
Floor Tile - Kitchen	Unfunded									
Ground Light Allowance	Unfunded									
Interior Painting	Unfunded									
Irrigation System	Unfunded									
Landscaping	Unfunded									
Mail Box Pedestals	Unfunded									
Metal Benches - Playground	Unfunded									
Metal Benches - Tennis	Unfunded									
Metal Picnic Tables - Playground	Unfunded									
Metal Picnic Tables - Tennis Pavilion	Unfunded									
Plastic Play Surface Border	Unfunded									
Plumbing Piping In Building	Unfunded									
Pond Fountain Allowance (4 year cycle)	Unfunded									
Pool Lift	Unfunded									
Pool Shell	Unfunded									
Post Swing Single Bay	Unfunded									
Refrigerator	Unfunded									

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Description										
Components Not Included continued										
Refurbishment Allowance - Sign Monuments	Unfunded									
Rubber Flooring - Fitness Center	Unfunded									
Shade Structure Frame	Unfunded									
Standing Seam Metal Panels - Entry Feature	Unfunded									
Street Resurfacing	Unfunded									
Tennis Court Replacement	Unfunded									
Utility Lines to Building	Unfunded									
Vinyl Ceiling - Tennis Pavilion	Unfunded									
Vinyl Gates - Dumpster	Unfunded									
Wall Mirrors	Unfunded									
Wall Over/Microwave	Unfunded									
Water Coolers	Unfunded									
Water Heater	Unfunded									
Wiring In Building	Unfunded									
Wood Flooring Refinish - Club Room	Unfunded									
Wood Siding/Brick - Clubhouse	Unfunded									
Year Total:	15,400		7,270	10,854			9,509	142,119		

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Beginning Balance	243,817	191,584	236,586	225,231	250,561	288,743	313,461	367,458	239,963	227,468
Annual Assessment	39,188	40,363	41,574	42,821	44,106	45,429	46,792	48,196	49,642	51,131
Interest Earned	3,757	4,639	4,416	4,913	5,662	6,146	7,205	4,705	4,460	5,572
Expenditures	95,178		57,346	22,404	11,586	26,857		180,396	66,597	
Fully Funded Reserves	399,010	447,204	438,778	466,937	507,892	535,246	591,868	466,080	454,900	512,837
Percent Fully Funded	48%	53%	51%	54%	57%	59%	62%	51%	50%	55%
Ending Balance	191,584	236,586	225,231	250,561	288,743	313,461	367,458	239,963	227,468	284,171
Description										
Misc. Site Components										
Street Signs/Poles								25,563		
Wood Bulkhead - Retention Pond								9,434		
Wood Pergola Entry Feature Repair/Replace			18,290							
Wood Pilings 50%/Stringers/Deck - Pier				13,443						
Misc. Site Components Total:			18,290	13,443				34,997		
Fencing & Gates										
Aluminum Fence - Pool						26,857				
Aluminum Railing - Rear Patio/Ramp									12,009	
Chain Link Coated Fence 10 Ft - Tennis Courts			18,344							
Vinyl Ranch Fence - Entry								29,240		-
Fencing & Gates Total:			18,344			26,857		29,240	12,009	
Site Lighting										
Decorative Light Poles - Pool								21,911		
Decorative Light Poles - Site								49,300		
Wall Laterns - Entry Feature								10,043		
Site Lighting Total:								81,254		
Misc. Building Components										
Restroom Refurbish Allowance - Club Room										
Restroom Refurbish Allowance - Pool/Fitness										
Wood Cabinets/Stone Top - Kitchen										
Wood Decking - Covered Porch										
Misc. Building Components Total:		<u> </u>								

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Description										
Roofing										
Asphalt Shingles (Arch) - Clubhouse										
Standing Seam Metal Panels - Clubhouse								9,038		
Roofing Total:								9,038		
Exterior Painting										
Clubhouse					11,586					
Exterior Painting Total:					11,586					
Furniture Fixtures & Equipment										
Furniture Allowance - Club Room										
Furniture Allowance - Patio/Deck				8,960						
Furniture Allowance - Pool Deck									54,588	
Shade Structure Fabric								10,530		
Furniture Fixtures & Equipment Total:				8,960				10,530	54,588	
HVAC										
Heat Pump 5 Ton			9,414							
Heat Pump 6 Ton			11,297							
HVAC Total:			20,711							
Swimming Pool										
Concrete Pavers/Pool Deck/Patio										
Filtration Refurbishment Allowance										
Pool Resurfacing/Tile	82,276									
Swimming Pool Total:	82,276									
Tennis Courts										
Asphalt Resurfacing (Color Coat)	12,902							15,336		
Tennis Courts Total:	12,902							15,336		
Playground										
Play Equipment Allowance										
Playground Total:										

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Description										
Components Not Included										
Access Controller/Devices - Amenity	Unfunded									
Aluminum Gutters/DS - Clubhouse	Unfunded									
Asphalt Seal Coat - Parking Lot	Unfunded									
Asphalt Shingles (Arch) - Pier Pavilion	Unfunded									
Asphalt Shingles (Arch) - Tennis Pavilion	Unfunded									
Backstop - Tennis Courts	Unfunded									
Brick Wall Cleaning/Repair/Replace	Unfunded									
Carpet - Office/Storage	Unfunded									
Catch Basin Repair	Unfunded									
Concrete Curb/Walk Allowance - Parking Lot	Unfunded									
Concrete Pavers Majestic Walk Blvd.	Unfunded									
Drainage Structures/Pipe	Unfunded									
Entry Feature	Unfunded									
Fitness Equipment (Partial Replacement)	Unfunded									
Fitness Equipment Allowance (Full Replacemen	Unfunded									
Floor Tile - Kitchen	Unfunded									
Ground Light Allowance	Unfunded									
Interior Painting	Unfunded									
Irrigation System	Unfunded									
Landscaping	Unfunded									
Mail Box Pedestals	Unfunded									
Metal Benches - Playground	Unfunded									
Metal Benches - Tennis	Unfunded									
Metal Picnic Tables - Playground	Unfunded									
Metal Picnic Tables - Tennis Pavilion	Unfunded									
Plastic Play Surface Border	Unfunded									
Plumbing Piping In Building	Unfunded									
Pond Fountain Allowance (4 year cycle)	Unfunded									
Pool Lift	Unfunded									
Pool Shell	Unfunded									
Post Swing Single Bay	Unfunded									
Refrigerator	Unfunded									

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Description										
Components Not Included continued										
Refurbishment Allowance - Sign Monuments	Unfunded									
Rubber Flooring - Fitness Center	Unfunded									
Shade Structure Frame	Unfunded									
Standing Seam Metal Panels - Entry Feature	Unfunded									
Street Resurfacing	Unfunded									
Tennis Court Replacement	Unfunded									
Utility Lines to Building	Unfunded									
Vinyl Ceiling - Tennis Pavilion	Unfunded									
Vinyl Gates - Dumpster	Unfunded									
Wall Mirrors	Unfunded									
Wall Over/Microwave	Unfunded									
Water Coolers	Unfunded									
Water Heater	Unfunded									
Wiring In Building	Unfunded									
Wood Flooring Refinish - Club Room	Unfunded									
Wood Siding/Brick - Clubhouse	Unfunded									
Year Total:	95,178		57,346	22,404	11,586	26,857		180,396	66,597	

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Beginning Balance Annual Assessment Interest Earned	284,171 52,665 6,737	343,573 54,245 7,956	405,774 55,872 1,933	98,575 57,548 2,489	126,938 59,275 2,803	142,931 61,053 4,080	208,064 62,885 5,419	276,368 64,771 3,723	189,895 66,714 4,100	209,096 68,716 5,556
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	573,388 60% 343,573	636,645 64% 405,774	365,004 328,578 30% 98,575	31,675 355,725 36% 126,938	46,084 370,067 39% 142,931	433,320 48% 208,064	499,504 55% 276,368	154,967 409,886 46% 189,895	51,613 425,383 49% 209,096	495,626 57% 283,368
Description Misc. Site Components Street Signs/Poles Wood Bulkhead - Retention Pond Wood Pergola Entry Feature Repair/Replace Wood Pilings 50%/Stringers/Deck - Pier									19,470	
Misc. Site Components Total: Fencing & Gates Aluminum Fence - Pool Aluminum Railing - Rear Patio/Ramp Chain Link Coated Fence 10 Ft - Tennis Courts Vinyl Ranch Fence - Entry Fencing & Gates Total:									19,470	
Site Lighting Decorative Light Poles - Pool Decorative Light Poles - Site Wall Laterns - Entry Feature Site Lighting Total:										
Misc. Building Components Restroom Refurbish Allowance - Club Room Restroom Refurbish Allowance - Pool/Fitness Wood Cabinets/Stone Top - Kitchen Wood Decking - Covered Porch Misc. Building Components Total:				16,676 16,676				28,048 67,199 95,247	19,166 19,166	

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Description										
Roofing										
Asphalt Shingles (Arch) - Clubhouse								59,720		
Standing Seam Metal Panels - Clubhouse										
Roofing Total:								59,720		
Exterior Painting										
Clubhouse			14,117							
Exterior Painting Total:			14,117							
Furniture Fixtures & Equipment										
Furniture Allowance - Club Room				14,999						
Furniture Allowance - Patio/Deck				,					12,977	
Furniture Allowance - Pool Deck										
Shade Structure Fabric										
Furniture Fixtures & Equipment Total:				14,999					12,977	
HVAC										
Heat Pump 5 Ton					12,661					
Heat Pump 6 Ton					15,193					
HVAC Total:					27,854					
Swimming Pool										
Concrete Pavers/Pool Deck/Patio			130,054							
Filtration Refurbishment Allowance			41,318							
Pool Resurfacing/Tile			110,652							
Swimming Pool Total:			282,024							
Tennis Courts										
Asphalt Resurfacing (Color Coat)					18,230					
Tennis Courts Total:					18,230					
Playground										
Play Equipment Allowance			68,863							
Playground Total:			68,863							
• • • • • • • • • • • • • • • • • • • •			,							

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Description										
Components Not Included										
Access Controller/Devices - Amenity	Unfunded									
Aluminum Gutters/DS - Clubhouse	Unfunded									
Asphalt Seal Coat - Parking Lot	Unfunded									
Asphalt Shingles (Arch) - Pier Pavilion	Unfunded									
Asphalt Shingles (Arch) - Tennis Pavilion	Unfunded									
Backstop - Tennis Courts	Unfunded									
Brick Wall Cleaning/Repair/Replace	Unfunded									
Carpet - Office/Storage	Unfunded									
Catch Basin Repair	Unfunded									
Concrete Curb/Walk Allowance - Parking Lot	Unfunded									
Concrete Pavers Majestic Walk Blvd.	Unfunded									
Drainage Structures/Pipe	Unfunded									
Entry Feature	Unfunded									
Fitness Equipment (Partial Replacement)	Unfunded									
Fitness Equipment Allowance (Full Replacemen	Unfunded									
Floor Tile - Kitchen	Unfunded									
Ground Light Allowance	Unfunded									
Interior Painting	Unfunded									
Irrigation System	Unfunded									
Landscaping	Unfunded									
Mail Box Pedestals	Unfunded									
Metal Benches - Playground	Unfunded									
Metal Benches - Tennis	Unfunded									
Metal Picnic Tables - Playground	Unfunded									
Metal Picnic Tables - Tennis Pavilion	Unfunded									
Plastic Play Surface Border	Unfunded									
Plumbing Piping In Building	Unfunded									
Pond Fountain Allowance (4 year cycle)	Unfunded									
Pool Lift	Unfunded									
Pool Shell	Unfunded									
Post Swing Single Bay	Unfunded									
Refrigerator	Unfunded									

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Description										
Components Not Included continued										
Refurbishment Allowance - Sign Monuments	Unfunded									
Rubber Flooring - Fitness Center	Unfunded									
Shade Structure Frame	Unfunded									
Standing Seam Metal Panels - Entry Feature	Unfunded									
Street Resurfacing	Unfunded									
Tennis Court Replacement	Unfunded									
Utility Lines to Building	Unfunded									
Vinyl Ceiling - Tennis Pavilion	Unfunded									
Vinyl Gates - Dumpster	Unfunded									
Wall Mirrors	Unfunded									
Wall Over/Microwave	Unfunded									
Water Coolers	Unfunded									
Water Heater	Unfunded									
Wiring In Building	Unfunded									
Wood Flooring Refinish - Club Room	Unfunded									
Wood Siding/Brick - Clubhouse	Unfunded									
Year Total:			365,004	31,675	46,084			154,967	51,613	

Description	Expenditures
Replacement Year 20-21	
HVAC	
Heat Pump 5 Ton	7,000
Heat Pump 6 Ton	8,400
Total for 2020 - 2021	\$15,400
No Replacement in 21-22	
Replacement Year 22-23	
Furniture Fixtures & Equipment	
Shade Structure Fabric	7,270
Total for 2022 - 2023	\$7,270
Replacement Year 23-24	
Tennis Courts	
Asphalt Resurfacing (Color Coat)	10,854
Total for 2023 - 2024	\$10,854
No Replacement in 24-25	
No Replacement in 25-26	
Replacement Year 26-27	
Exterior Painting	
Clubhouse	9,509
Total for 2026 - 2027	\$9,509
Replacement Year 27-28	
Misc. Building Components	
Restroom Refurbish Allowance - Club Room	17,117
Restroom Refurbish Allowance - Pool/Fitness	41,010
Roofing	
Asphalt Shingles (Arch) - Clubhouse	36,445
Playground	
Play Equipment Allowance	47,547
Total for 2027 - 2028	\$142,119

Description	Expenditures
No Replacement in 28-29	
No Replacement in 29-30	
Replacement Year 30-31	
Swimming Pool Pool Resurfacing/Tile	82,276
Tennis Courts	02,270
Asphalt Resurfacing (Color Coat)	12,902
Total for 2030 - 2031	\$95,178
No Replacement in 31-32	
Replacement Year 32-33	
Misc. Site Components	
Wood Pergola Entry Feature Repair/Replace	18,290
Fencing & Gates	10.244
Chain Link Coated Fence 10 Ft - Tennis Courts	18,344
HVAC Heat Pump 5 Ton	9,414
Heat Pump 6 Ton	11,297
Total for 2032 - 2033	\$57,346
Replacement Year 33-34	
Misc. Site Components	
Wood Pilings 50%/Stringers/Deck - Pier	13,443
Furniture Fixtures & Equipment	
Furniture Allowance - Patio/Deck	8,960
Total for 2033 - 2034	\$22,404
Replacement Year 34-35	
Exterior Painting	11 502
Clubhouse	11,586
Total for 2034 - 2035	\$11,586


Description	Expenditures
Replacement Year 35-36	
Fencing & Gates	
Aluminum Fence - Pool	26,857
Total for 2035 - 2036	\$26,857
No Replacement in 36-37	
Replacement Year 37-38	
Misc. Site Components	
Street Signs/Poles	25,563
Wood Bulkhead - Retention Pond	9,434
Fencing & Gates	
Vinyl Ranch Fence - Entry	29,240
Site Lighting	
Decorative Light Poles - Pool	21,911
Decorative Light Poles - Site	49,300
Wall Laterns - Entry Feature	10,043
Roofing	
Standing Seam Metal Panels - Clubhouse	9,038
Furniture Fixtures & Equipment	
Shade Structure Fabric	10,530
Tennis Courts	
Asphalt Resurfacing (Color Coat)	15,336
Total for 2037 - 2038	\$180,396
Replacement Year 38-39	
Fencing & Gates	
Aluminum Railing - Rear Patio/Ramp	12,009
Furniture Fixtures & Equipment	
Furniture Allowance - Pool Deck	54,588
Total for 2038 - 2039	\$66,597
No Replacement in 39-40	
N. D. 1	

No Replacement in 40-41

Description	Expenditures
No Replacement in 41-42	
Replacement Year 42-43	
Exterior Painting	14.117
Clubhouse	14,117
Swimming Pool Congress Payons/Pool Pools/Patie	120.054
Concrete Pavers/Pool Deck/Patio Filtration Refurbishment Allowance	130,054 41,318
Pool Resurfacing/Tile	110,652
Playground	110,002
Play Equipment Allowance	68,863
Total for 2042 - 2043	\$365,004
Replacement Year 43-44	
Misc. Building Components	
Wood Cabinets/Stone Top - Kitchen	16,676
Furniture Fixtures & Equipment	
Furniture Allowance - Club Room	14,999
Total for 2043 - 2044	\$31,675
Replacement Year 44-45	
HVAC	
Heat Pump 5 Ton	12,661
Heat Pump 6 Ton	15,193
Tennis Courts	10.220
Asphalt Resurfacing (Color Coat)	18,230
Total for 2044 - 2045	\$46,084
No Replacement in 45-46	
No Replacement in 46-47	
Replacement Year 47-48	
Misc. Building Components	
Restroom Refurbish Allowance - Club Room	28,048

Description	Expenditures
Replacement Year 47-48 continued Restroom Refurbish Allowance - Pool/Fitness	67,199
Roofing	31,222
Asphalt Shingles (Arch) - Clubhouse	59,720
Total for 2047 - 2048	\$154,967
Replacement Year 48-49	
Misc. Site Components	
Wood Pilings 50%/Stringers/Deck - Pier	19,470
Misc. Building Components	
Wood Decking - Covered Porch	19,166
Furniture Fixtures & Equipment	
Furniture Allowance - Patio/Deck	12,977
Total for 2048 - 2049	\$51,613

Amelia Walk CDD No Streets Asset Current Cost by Category



Component Condition Assessment

Misc. Site Components

- Street signs and poles should be cleaned and painted upon inspection.
- Wood bulkhead and pier appear good condition from visual inspection of above waterline areas.

Fencing & Gates

- Fencing, gates, railings appear in good condition.
- Tennis court fencing requires some immediate cleaning and repair.

Site Lighting

• District has variety of site lighting that appears in good condition. Site visit was conducted during daytime hours, so performance of lights is unknown.

Misc. Building Components

- Restroom refurbishment allowance is included to allow flexibility for material selection determined at the time of replacement.
- Wood cabinets and top are like new.
- Wood decking at covered porch is like new.

Roofing

- Asphalt shingles have been installed on the new section of the clubhouse and do not match the existing. At the time of replacement of the original roof this area is included. Shingle areas should be inspected annually, and repairs completed.
- Metal roofing appears in good condition and should be inspected annually, and repairs completed.

Exterior Painting

• Exterior walls should be properly prepared prior to painting with all material joints sealed, window and door connections to siding sealed.

FF&E

- Furniture allowances for interior and exterior spaces in included.
- Shade structures at pool should not need replacement with regular repair. Immediate repair and painting are needed.
- Shade fabric is near end of its useful life.

HVAC

• Clubhouse has two heat pumps that we assume are original equipment. Generally, this component has a 12-year life. Annual inspection and cleaning of units is recommended.

Swimming Pool

- Concrete pool deck pavers appear structurally sound, but we find over time the aggregate begins to appear due to wear and do not provide the level of quality the District will expect.
- An allowance for major filtration refurbishment is included for pumps, motors and other equipment.
- Pool was resurfaced in 2019 and in good condition.

Tennis Court

• Tennis court resurfacing is included on a 7-year cycle.

Playground

• Play equipment and swings appear in good condition. An inspection is recommended annually with needed repairs completed.

Amelia Walk CDD No Streets Component Inventory

			eji.		A partie de la	\$0		
	Oge Str	ځي ځي ده څيو	ية الله من عالم	} **	Street	jāt. Sālās	* *	Catalog Casa
Description	ئ _ي جي	\$6,76	3 23	Ø.	₹°	2 tr	المنات للمنات	0,0
Misc. Site Components								
Street Signs/Poles	07-08	37-38	30	0	17	14 Each	1,200.00	16,800
Wood Bulkhead - Retention Pond	07-08	37-38	30	0	17	40 Linear Feet	155.00	6,200
Wood Pergola Entry Feature Repair/Replace	e 07-08	32-33	25	0	12	2 Each	6,800.00	13,600
Wood Pilings 50%/Stringers/Deck - Pier Misc. Site Components - Total	18-19	33-34	15	0	13	106 Square Feet	92.00	9,752 \$46,352
Fencing & Gates								
Aluminum Fence - Pool	10-11	35-36	25	0	15	488 Linear Feet	38.00	18,544
Aluminum Railing - Rear Patio/Ramp	10-11	38-39	28	0	18	140 Linear Feet	55.00	7,700
Chain Link Coated Fence 10 Ft - Tennis C.		32-33	25	0	12	440 Linear Feet		13,640
Vinyl Ranch Fence - Entry Fencing & Gates - Total	07-08	37-38	30	0	17	778 Linear Feet	24.70	19,217 \$59,101
Gu Ti Lu								
Site Lighting	07.00	27.20	20	_	1.7	4.5. 1	2 (00 00	1.4.400
Decorative Light Poles - Pool	07-08	37-38	30	0	17	4 Each	3,600.00	14,400
Decorative Light Poles - Site	07-08 07-08	37-38 37-38	30 30	0	17 17	9 Each 3 Each	3,600.00	32,400
Wall Laterns - Entry Feature Site Lighting - Total	07-08	37-36	30	U	17	3 Each	2,200.00	$\frac{6,600}{$53,400}$
Misc. Building Components								
Restroom Refurbish Allowance - Club Roo.	. 07-08	27-28	20	0	7	200 Square Feet	72.00	14,400
Restroom Refurbish Allowance - Pool/Fitn	. 07-08	27-28	20	0	7	460 Square Feet		34,500
Wood Cabinets/Stone Top - Kitchen	18-19	43-44	25	0	23	21 Linear Feet	450.00	9,450
Wood Decking - Covered Porch	18-19	48-49	30	0	28	800 Square Feet	12.00	9,600
Misc. Building Components - Total								\$67,950
Roofing								
Asphalt Shingles (Arch) - Clubhouse	07-08	27-28	20	0	7	73 Squares	420.00	30,660
Standing Seam Metal Panels - Clubhouse Roofing - Total	07-08	37-38	30	0	17	540 Square Feet	11.00	<u>5,940</u> \$36,600
Exterior Painting								
Clubhouse	18-19	26-27	8	0	6	1 Lump Sum	8,200.00	8,200
Exterior Painting - Total						1	,	\$8,200
Furniture Fixtures & Equipment								
Furniture Allowance - Club Room	18-19	43-44	25	0	23	1 Lump Sum	8,500.00	8,500
Furniture Allowance - Patio/Deck	18-19	33-34	15	0	13	1 Lump Sum	6,500.00	6,500
Furniture Allowance - Pool Deck	18-19	38-39	20	0	18	1 Lump Sum	35,000.00	35,000
Shade Structure Fabric	07-08	22-23	15	0	2	2 Each	3,460.00	6,920
Furniture Fixtures & Equipment - Total								\$56,920

Amelia Walk CDD No Streets Component Inventory

	Ogic Say	_چ ې ر _ې چې	is Jest	<u>ک</u> خ	stront s	jiro	v. X	Ä,
Description	كيهم بحور	500 76	\$ 5°	A	2 Sells	Jill [®]	عاملة للمعالمة	CHE COST
HVAC								
Heat Pump 5 Ton	07-08	20-21	12	0	0	1 Each	7,000.00	7,000
Heat Pump 6 Ton	07-08	20-21	12	0	0	1 Each	8,400.00	8,400
HVAC - Total								\$15,400
Swimming Pool								
Concrete Pavers/Pool Deck/Patio	07-08	42-43	35	0	22	9,443 Square Fee	et 8.00	75,544
Filtration Refurbishment Allowance	07-08	42-43	35	0	22	1 Lump Sum		24,000
Pool Resurfacing/Tile	18-19	30-31	12	0	10	4,591 Square Fee	et 14.00	64,274
Swimming Pool - Total								\$163,818
Tennis Courts								
Asphalt Resurfacing (Color Coat)	07-08	23-24	7	9	3	1,362 Square Yar	rds 7.40	10,079
Tennis Courts - Total								\$10,079
Playground								
Play Equipment Allowance	07-08	27-28	15	5	7	1 Lump Sum	40 000 00	40,000
Playground - Total	0, 00	2, 20			,	1 20mp 8 mm	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	\$40,000
Components Not Included								
Access Controller/Devices - Amenity		nfunded						
Aluminum Gutters/DS - Clubhouse		nfunded						
Asphalt Seal Coat - Parking Lot		nfunded						
Asphalt Shingles (Arch) - Pier Pavilion		nfunded						
Asphalt Shingles (Arch) - Tennis Pavilion		nfunded						
Backstop - Tennis Courts		nfunded						
Brick Wall Cleaning/Repair/Replace Carpet - Office/Storage		nfunded nfunded						
Catch Basin Repair		nfunded						
Concrete Curb/Walk Allowance - Parking		nfunded						
Concrete Pavers Majestic Walk Blvd.		nfunded						
Drainage Structures/Pipe		nfunded						
Entry Feature		nfunded						
Fitness Equipment (Partial Replacement)		nfunded						
Fitness Equipment Allowance (Full Replac.		nfunded						
Floor Tile - Kitchen	U	nfunded						
Ground Light Allowance	U	nfunded						
Interior Painting		nfunded						
Irrigation System		nfunded						
Landscaping		nfunded						
Mail Box Pedestals		nfunded						
Metal Benches - Playground		nfunded						
Metal Benches - Tennis Metal Biopia Tables - Playground		nfunded						
Metal Picnic Tables - Playground Metal Picnic Tables - Tennis Pavilion		nfunded						
wictal Fichic Tables - Tellills Pavillon	U	nfunded						

Amelia Walk CDD No Streets **Component Inventory**

	is is		چر.	·x ×	restr.
Description	Outo Serve	43 74 2 2 4 4 1 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Thir	120 COS	Car, Cos

Components Not Included continued... Plastic Play Surface Border Unfunded Plumbing Piping In Building Unfunded Pond Fountain Allowance (4 year cycle) Unfunded Unfunded Pool Lift Pool Shell Unfunded Post Swing Single Bay Unfunded Refrigerator Unfunded Refurbishment Allowance - Sign Monume.. Unfunded Rubber Flooring - Fitness Center Unfunded Shade Structure Frame Unfunded Standing Seam Metal Panels - Entry Featu.. Unfunded Street Resurfacing Unfunded Unfunded Unfunded Unfunded

Tennis Court Replacement Utility Lines to Building Vinyl Ceiling - Tennis Pavilion Vinyl Gates - Dumpster Unfunded Wall Mirrors Unfunded Wall Over/Microwave Unfunded

Water Coolers Water Heater Wiring In Building Wood Flooring Refinish - Club Room Wood Siding/Brick - Clubhouse

Components Not Included - Total

\$557,819 **Total Asset Summary**

Unfunded

Unfunded

Unfunded

Unfunded

Unfunded

Amelia Walk CDD No Streets Component Detail Index

Asset IDDescription		Replacement	Page	
Misc. S	Site Components			
1064	Street Signs/Poles	37-38	5-9	
1044	Wood Bulkhead - Retention Pond	37-38	5-9	
1067	Wood Pergola Entry Feature Repair/Replace	32-33	5-10	
1043	Wood Pilings 50%/Stringers/Deck - Pier	33-34	5-10	
Fencin	g & Gates			
1026	Aluminum Fence - Pool	35-36	5-11	
1034	Aluminum Railing - Rear Patio/Ramp	38-39	5-11	
1060	Chain Link Coated Fence 10 Ft - Tennis Courts	32-33	5-12	
1053	Vinyl Ranch Fence - Entry	37-38	5-12	
Site Li	ghting			
1035	Decorative Light Poles - Pool	37-38	5-13	
1046	Decorative Light Poles - Site	37-38	5-13	
1066	Wall Laterns - Entry Feature	37-38	5-14	
Misc. H	Building Components			
1014	Restroom Refurbish Allowance - Club Room	27-28	5-15	
1015	Restroom Refurbish Allowance - Pool/Fitness	27-28	5-15	
1016	Wood Cabinets/Stone Top - Kitchen	43-44	5-16	
1017	Wood Decking - Covered Porch	48-49	5-16	
Roofin	g			
1003	Asphalt Shingles (Arch) - Clubhouse	27-28	5-17	
1004	Standing Seam Metal Panels - Clubhouse	37-38	5-17	
Exterior Painting				
1006	Clubhouse	26-27	5-18	
Furnit	ıre Fixtures & Equipment			
1022	Furniture Allowance - Club Room	43-44	5-19	
1028	Furniture Allowance - Patio/Deck	33-34	5-19	
1040	Furniture Allowance - Pool Deck	38-39	5-20	
1038	Shade Structure Fabric	22-23	5-20	
HVAC				
1010	Heat Pump 5 Ton	20-21	5-21	

Amelia Walk CDD No Streets Component Detail Index

Asset I	DDescription	Replacement	Page
HVAC	Continued		
1009	Heat Pump 6 Ton	20-21	5-21
	-		
	ning Pool		
1029	Concrete Pavers/Pool Deck/Patio	42-43	5-22
1051	Filtration Refurbishment Allowance	42-43	5-22
1036	Pool Resurfacing/Tile	30-31	5-22
Tennis	Courts		
1061	Asphalt Resurfacing (Color Coat)	23-24	5-24
1001	rispinal resultating (color cont)	23 2 1	5 21
Playgr	ound		
1055	Play Equipment Allowance	27-28	5-25
~			
_	onents Not Included	TT 0 1 1	7 0 -
1019	Access Controller/Devices - Amenity	Unfunded	5-26
1024	Aluminum Gutters/DS - Clubhouse	Unfunded	5-26
1074	Asphalt Seal Coat - Parking Lot	Unfunded	5-26
1001	Asphalt Shingles (Arch) - Pier Pavilion	Unfunded	5-27
1002	Asphalt Shingles (Arch) - Tennis Pavilion	Unfunded	5-27
1062	Backstop - Tennis Courts	Unfunded	5-28
1076	Brick Wall Cleaning/Repair/Replace	Unfunded	5-28
1057	Carpet - Office/Storage	Unfunded	5-28
1047	Catch Basin Repair	Unfunded	5-29
1008	Concrete Curb/Walk Allowance - Parking Lot	Unfunded	5-29
1070	Concrete Pavers Majestic Walk Blvd.	Unfunded	5-29
1058	Drainage Structures/Pipe	Unfunded	5-30
1065	Entry Feature	Unfunded	5-30
1031	Fitness Equipment (Partial Replacement)	Unfunded	5-30
1030	Fitness Equipment Allowance (Full Replacement)	Unfunded	5-31
1013	Floor Tile - Kitchen	Unfunded	5-31
1050	Ground Light Allowance	Unfunded	5-32
1077	Interior Painting	Unfunded	5-32
1079	Irrigation System	Unfunded	5-32
1078	Landscaping	Unfunded	5-32
1068	Mail Box Pedestals	Unfunded	5-33
1054	Metal Benches - Playground	Unfunded	5-33
1063	Metal Benches - Tennis	Unfunded	5-33

Amelia Walk CDD No Streets Component Detail Index

Asset I	DDescription	Replacement	Page
Сотро	nents Not Included Continued		
1075	Metal Picnic Tables - Playground	Unfunded	5-34
1059	Metal Picnic Tables - Tennis Pavilion	Unfunded	5-34
1052	Plastic Play Surface Border	Unfunded	5-35
1081	Plumbing Piping In Building	Unfunded	5-35
1041	Pond Fountain Allowance (4 year cycle)	Unfunded	5-35
1039	Pool Lift	Unfunded	5-36
1072	Pool Shell	Unfunded	5-36
1056	Post Swing Single Bay	Unfunded	5-37
1021	Refrigerator	Unfunded	5-37
1023	Refurbishment Allowance - Sign Monuments	Unfunded	5-38
1033	Rubber Flooring - Fitness Center	Unfunded	5-38
1037	Shade Structure Frame	Unfunded	5-39
1005	Standing Seam Metal Panels - Entry Feature	Unfunded	5-39
1088	Street Resurfacing	Unfunded	5-39
1071	Tennis Court Replacement	Unfunded	5-40
1080	Utility Lines to Building	Unfunded	5-40
1073	Vinyl Ceiling - Tennis Pavilion	Unfunded	5-40
1048	Vinyl Gates - Dumpster	Unfunded	5-41
1032	Wall Mirrors	Unfunded	5-41
1020	Wall Over/Microwave	Unfunded	5-41
1011	Water Coolers	Unfunded	5-42
1012	Water Heater	Unfunded	5-42
1082	Wiring In Building	Unfunded	5-42
1018	Wood Flooring Refinish - Club Room	Unfunded	5-43
1025	Wood Siding/Brick - Clubhouse	Unfunded	5-43
	Total Funded Assets	29	
	Total Unfunded Assets	<u>48</u>	
	Total Assets	77	

Amelia Walk CDD No Streets Component Detail

Street Signs/Poles - 2037

Asset ID 1064 Asset Cost \$16,800.00
Percent Replacement 100%
Misc. Site Components Future Cost \$25,563.19

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
January 2008
37-38



Wood Bulkhead - Retention Pond - 2037

Asset ID 1044 Asset Cost \$6,200.00
Percent Replacement 100%
Misc. Site Components Future Cost \$9,434.03

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
317-38



Amelia Walk CDD No Streets Component Detail

Wood Pergola Entry Feature Repair/Replace - 2032

		2 Each	@ \$6,800.00
Asset ID	1067	Asset Cost	\$13,600.00
		Percent Replacement	100%
N	lisc. Site Components	Future Cost	\$18,290.49
Placed in Service	January 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	12		



Wood Pilings 50%/Stringers/Deck - Pier - 2033

Asset ID	1043	106 Square Feet Asset Cost Percent Replacement	@ \$92.00 \$9,752.00 100%
N	Aisc. Site Components	Future Cost	\$13,443.24
Placed in Service	January 2019		
Useful Life	15		
Replacement Year	33-34		
Remaining Life	13		



Community Advisors Page 5-10 June 4, 2020

Aluminum Fence - Pool - 2035

@ \$38.00 Asset ID 1026 Asset Cost \$18,544.00 Percent Replacement 100% Future Cost Fencing & Gates \$26,857.24

488 Linear Feet

Placed in Service January 2011 Useful Life 25 Replacement Year 35-36 Remaining Life 15



Aluminum Railing - Rear Patio/Ramp - 2038

140 Linear Feet @ \$55.00 Asset ID 1034 Asset Cost \$7,700.00 Percent Replacement 100% Fencing & Gates **Future Cost** \$12,009.37

Placed in Service January 2011 Useful Life 28 Replacement Year 38-39 Remaining Life 18



Chain Link Coated Fence 10 Ft - Tennis Courts - 2032

		440 Linear Feet	@ \$31.00
Asset ID	1060	Asset Cost	\$13,640.00
		Percent Replacement	100%
	Fencing & Gates	Future Cost	\$18,344.28
Placed in Service	January 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	12		



Vinyl Ranch Fence - Entry - 2037

Placed in Service Useful Life

Asset ID 1053

Fencing & Gates January 2008 30 37-38


Replacement Year 37-38 Remaining Life 17 778 Linear Feet @ \$24.70
Asset Cost \$19,216.60
Percent Replacement 100%
Future Cost \$29,240.33



Decorative Light Poles - Pool - 2037

Asset ID 1035

Placed in Service January 2008
Useful Life 30
Replacement Year 37-38
Remaining Life 17



Decorative Light Poles - Site - 2037

Asset ID 1046

Placed in Service
Useful Life
Replacement Year
Remaining Life

Site Lighting
January 2008
30
37-38





Wall Laterns - Entry Feature - 2037

Asset ID 1066 Asset Cost 96,600.00
Percent Replacement 100%
Site Lighting Future Cost \$10,042.68

Placed in Service
Useful Life
Replacement Year
Remaining Life
January 2008
37-38
17



Restroom Refurbish Allowance - Club Room - 2027

Asset ID 1014 Asset Cost \$14,400.00
Percent Replacement 100%
Misc. Building Components Future Cost \$17,117.07

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2008
27-28
7



Restroom Refurbish Allowance - Pool/Fitness - 2027

Asset ID 1015 Asset Cost \$34,500.00
Percent Replacement 100%
Misc. Building Components Future Cost \$41,009.66

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2008
27-28
7





Wood Cabinets/Stone Top - Kitchen - 2043

21 Linear Feet @ \$450.00 1016 Asset ID Asset Cost \$9,450.00 Percent Replacement 100% Misc. Building Components **Future Cost** \$16,675.57

January 2019 Placed in Service Useful Life 25 43-44 Replacement Year Remaining Life 23





Wood Decking - Covered Porch - 2048

800 Square Feet @ \$12.00 1017 Asset Cost Asset ID \$9,600.00 Percent Replacement 100%

Misc. Building Components Placed in Service January 2019 Useful Life 30 Replacement Year 48-49 Remaining Life 28

Future Cost \$19,166.35



Asphalt Shingles (Arch) - Clubhouse - 2027

		73 Squares	@ \$420.00
Asset ID	1003	Asset Cost	\$30,660.00
		Percent Replacement	100%
	Roofing	Future Cost	\$36,445.10
Placed in Service	January 2008		
Useful Life	20		
Replacement Year	27-28		
Remaining Life	7		



Standing Seam Metal Panels - Clubhouse - 2037

Asset ID	1004	540 Square Feet Asset Cost	@ \$11.00 \$5,940.00
115500112	1001	Percent Replacement	100%
	Roofing	Future Cost	\$9,038.41
Placed in Service	January 2008		
Useful Life	30		
Replacement Year	37-38		
Remaining Life	17		



C1 11 2026			
Clubhouse - 2026		1 Lump Sum	@ \$8,200.00
Asset ID	1006	Asset Cost	\$8,200.00
		Percent Replacement	100%
	Exterior Painting	Future Cost	\$9,509.49
Placed in Service	January 2019		
Useful Life	8		
Replacement Year	26-27		
Remaining Life	6		



Furniture Allowance - Club Room - 2043

		1 Lump Sum	@ \$8,500.00
Asset ID	1022	Asset Cost	\$8,500.00
		Percent Replacement	100%
Furniture Fixtures	& Equipment	Future Cost	\$14,999.19

Placed in Service January 2019
Useful Life 25
Replacement Year 43-44
Remaining Life 23



Furniture Allowance - Patio/Deck - 2033

		1 Lump Sum	@ \$6,500.00
Asset ID	1028	Asset Cost	\$6,500.00
		Percent Replacement	100%
Furniture Fixtures & Equipment		Future Cost	\$8,960.32
Placed in Service	January 2019		
Useful Life	15		

33-34



Replacement Year





Furniture Allowance - Pool Deck - 2038

Asset ID 1040 Asset Cost \$35,000.00

Percent Replacement Furniture Fixtures & Equipment Future Cost \$54,588.05

Placed in Service January 2019
Useful Life 20
Replacement Year 38-39
Remaining Life 18



Shade Structure Fabric - 2022

Asset ID 1038 Asset Cost \$6,920.00

Percent Replacement Future Fixtures & Equipment Future Cost \$7,270.32

Furniture Fixtures & Equipment
Placed in Service January 2008
Useful Life 15
Replacement Year 22-23
Remaining Life 2





Heat Pump 5 Ton - 2020		1 Each	@ \$7,000.00
Asset ID	1010	Asset Cost	\$7,000.00
		Percent Replacement	100%
	HVAC	Future Cost	\$7,000.00
Placed in Service	January 2008		
Useful Life	12		
Replacement Year	20-21		
Remaining Life	0		
Heat Pump 6 Ton - 2020		1 Each	@ \$8,400.00
Asset ID	1009	Asset Cost	\$8,400.00
		Percent Replacement	100%
	HVAC	Future Cost	\$8,400.00
Placed in Service	January 2008		
Useful Life	12		
Replacement Year	20-21		
Remaining Life	0		

Concrete Pavers/Pool Deck/Patio - 2042

		9,443 Square Feet	@ \$8.00
Asset ID	1029	Asset Cost	\$75,544.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$130,054.39
Placed in Service	January 2008		

Placed in Service Useful Life 35 Replacement Year 42-43 Remaining Life 22





Filtration Refurbishment Allowance - 2042

		1 Lump Sum	@ \$24,000.00
Asset ID	1051	Asset Cost	\$24,000.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$41,317.71
Placed in Service	January 2008		
Useful Life	35		
Replacement Year	42-43		
Remaining Life	22		

Pool Resurfacing/Tile - 2030

Resurfacing/Tile - 20	030	4,591 Square Feet	@ \$14.00
Asset ID	1036	Asset Cost	\$64,274.00
		Percent Replacement	100%
	Swimming Pool	Future Cost	\$82,276.15
-1 11 0 1			

Placed in Service January 2019 Useful Life 12 Replacement Year 30-31 Remaining Life 10

Pool Resurfacing/Tile continued...



Asphalt Resurfacing (Color Coat) - 2023

Asset ID	1061	1,362 Square Yards Asset Cost Percent Replacement	@ \$7.40 \$10,078.80 100%
	Tennis Courts	Future Cost	\$10,853.77
Placed in Service	January 2008		
Useful Life	7		
Adjustment	9		
Replacement Year	23-24		
Remaining Life	3		



Play Equipment Allowance - 2027

y Equipment Allowance - 2027		1 Lump Sum	@ \$40,000.00
Asset ID	1055	Asset Cost	\$40,000.00
		Percent Replacement	100%
	Playground	Future Cost	\$47,547.43
D1 1' C'	T 2000		

January 2008 Placed in Service Useful Life 15 5 Adjustment Replacement Year 27-28 Remaining Life



Access Controller/Devices - Amenity

Asset ID 1019 Asset Cost

Percent Replacement
Components Not Included Future Cost

100%

Placed in Service January 2008 No Useful Life

Aluminum Gutters/DS - Clubhouse

Asset ID 1024 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost

Components Not Included Placed in Service January 2008

No Useful Life



Asphalt Seal Coat - Parking Lot

No Useful Life

Asset ID 1074 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost
Placed in Service January 2027

Community Advisors Page 5-26 June 4, 2020

Asphalt Seal Coat - Parking Lot continued...



Asphalt Shingles (Arch) - Pier Pavilion

Asset ID 1001

Components Not Included Placed in Service January 2008 No Useful Life Asset Cost
Percent Replacement 100%
Future Cost

Asphalt Shingles (Arch) - Tennis Pavilion

Asset ID 1002

Components Not Included Placed in Service January 2008 No Useful Life Asset Cost
Percent Replacement
Future Cost

Community Advisors Page 5-27 June 4, 2020

Asphalt Shingles (Arch) - Tennis Pavilion continued...



Backstop - Tennis Courts

No Useful Life

Asset ID 1062 Asset Cost

Components Not Included Future Cost
Placed in Service January 2008

Brick Wall Cleaning/Repair/Replace

Asset ID 1076 Asset Cost

100%

Percent Replacement 100%
Components Not Included Future Cost
Placed in Service January 2008
No Useful Life

Carpet - Office/Storage

No Useful Life

Asset ID 1057 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost
Placed in Service January 2008

Catch Basin Repair

Asset ID 1047 Asset Cost

Percent Replacement 100% **Future Cost**

Components Not Included Placed in Service January 2008 No Useful Life



Concrete Curb/Walk Allowance - Parking Lot

1008 Asset ID Asset Cost

Percent Replacement 100% Components Not Included **Future Cost** Placed in Service January 2017 No Useful Life

Concrete Pavers Majestic Walk Blvd.

Asset ID 1070 Asset Cost

Percent Replacement 100% **Future Cost** Components Not Included Placed in Service January 2008

Drainage Structures/Pipe

Asset ID 1058 Asset Cost

Percent Replacement Components Not Included Future Cost

100%

Placed in Service January 2008 No Useful Life

Entry Feature

Asset ID 1065 Asset Cost

Components Not Included Future Cost
Placed in Service January 2019

Percent Replacement 100%
Future Cost

No Useful Life



Fitness Equipment (Partial Replacement)

No Useful Life

Asset ID 1031 Asset Cost

Components Not Included Future Cost
Placed in Service January 2008

Percent Replacement 100%
Future Cost

Fitness Equipment Allowance (Full Replacement)

1030 Asset ID **Asset Cost**

Percent Replacement 100%

Future Cost Components Not Included January 2008 Placed in Service

No Useful Life





Future Cost

Floor Tile - Kitchen

Asset ID 1013 Asset Cost Percent Replacement 100%

Components Not Included January 2019 Placed in Service No Useful Life



Ground Light Allowance

Asset ID 1050 Asset Cost

Percent Replacement Components Not Included Future Cost

100%

Placed in Service January 2008

No Useful Life

Interior Painting

Asset ID 1077 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost

Placed in Service January 2008

No Useful Life

Irrigation System

Asset ID 1079 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost

Placed in Service January 2008

No Useful Life

Landscaping

Asset ID 1078 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost

Placed in Service January 2008

Mail Box Pedestals

Asset ID 1068 Asset Cost

Percent Replacement
Components Not Included Future Cost

100%

Placed in Service January 2008 No Useful Life

Metal Benches - Playground

No Useful Life

Asset ID 1054 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost
Placed in Service January 2008



Metal Benches - Tennis

No Useful Life

Asset ID 1063 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost
Placed in Service January 2008

Metal Benches - Tennis continued...



Metal Picnic Tables - Playground

Asset ID 1075

Components Not Included Placed in Service January 2008 No Useful Life Asset Cost
Percent Replacement
Future Cost

Metal Picnic Tables - Tennis Pavilion

Asset ID 1059

Components Not Included
Placed in Service January 2008
No Useful Life

Asset Cost Percent Replacement Future Cost

100%



Plastic Play Surface Border

Asset ID 1052 Asset Cost

Percent Replacement 100% **Future Cost** Components Not Included

Placed in Service January 2008 No Useful Life



Plumbing Piping In Building

Asset ID 1081 Asset Cost Percent Replacement

100%

Components Not Included Placed in Service January 2008

Future Cost No Useful Life

Pond Fountain Allowance (4 year cycle)

Asset ID 1041 Asset Cost

Percent Replacement 100% **Future Cost** Components Not Included Placed in Service January 2008

Pond Fountain Allowance (4 year cycle) continued...



Pool Lift

Asset ID 1039

Asset Cost Percent Replacement **Future Cost**

100%

Components Not Included Placed in Service January 2020 No Useful Life



Pool Shell

Asset ID 1072

Asset Cost Percent Replacement **Future Cost**

100%

Components Not Included Placed in Service No Useful Life

January 2008

Community Advisors Page 5-36 June 4, 2020

Post Swing Single Bay

Asset ID 1056 **Asset Cost**

Percent Replacement 100% Future Cost Components Not Included

January 2008 Placed in Service

No Useful Life



Refrigerator

Asset ID 1021 Asset Cost Percent Replacement 100%

Components Not Included January 2019 Placed in Service No Useful Life

Future Cost

Refurbishment Allowance - Sign Monuments

Asset ID 1023 Asset Cost

Percent Replacement 100% Future Cost

100%

Components Not Included Placed in Service January 2008

No Useful Life






Rubber Flooring - Fitness Center

Asset ID 1033 Asset Cost

Components Not Included Future Cost
Placed in Service January 2019



Shade Structure Frame

Asset ID 1037 Asset Cost

Percent Replacement
Components Not Included Future Cost

100%

Placed in Service January 2008

No Useful Life

Standing Seam Metal Panels - Entry Feature

Asset ID 1005 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost

Placed in Service January 2008

No Useful Life



Street Resurfacing

Asset ID 1088 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost
Placed in Service January 2008

Tennis Court Replacement

Asset ID 1071 Asset Cost

Percent Replacement Components Not Included Future Cost

100%

Placed in Service January 2008

No Useful Life

Utility Lines to Building

Asset ID 1080 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost

Components Not Included Placed in Service January 2008

No Useful Life

Vinyl Ceiling - Tennis Pavilion

Asset ID 1073 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost

Placed in Service January 2008



Vinyl Gates - Dumpster

Asset ID 1048 Asset Cost

Percent Replacement 100% Future Cost

100%

Components Not Included

Placed in Service January 2008

No Useful Life



Wall Mirrors

Asset ID 1032 Asset Cost

Percent Replacement
Components Not Included Future Cost

Placed in Service January 2008

No Useful Life

Wall Over/Microwave

Asset ID 1020 Asset Cost

Percent Replacement 100%
Components Not Included Future Cost

Placed in Service January 2019

No Useful Life

Community Advisors Page 5-41 June 4, 2020

Wall Over/Microwave continued...



Water Coolers

No Useful Life

Asset ID 1011

Components Not Included Placed in Service January 2008

Asset Cost
Percent Replacement
Future Cost

100%

100%

Water Heater

Asset ID 1012 Asset Cost

Components Not Included
Placed in Service January 2008
No Useful Life

Percent Replacement Future Cost

Wiring In Building

No Useful Life

Asset ID 1082 Asset Cost

Percent Replacement
Components Not Included
Future Cost
Placed in Service January 2008

Wood Flooring Refinish - Club Room

Asset ID 1018 Asset Cost

Percent Replacement
Components Not Included Future Cost

100%

Placed in Service January 2008
No Useful Life



Wood Siding/Brick - Clubhouse

Asset ID 1025 Asset Cost
Percent Replacement 100%

Future Cost

Components Not Included
Placed in Service January 2008
No Useful Life

METHODOLOGY

Reserve Analysis is a process that identifies capital expenses the District can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors and comparison of similar component cost found at other properties.

The funding plan we develop includes; adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. Percent Funded is defined by industry standards as 70-100% strong, 30-70% fair or adequate and below 30% weak or inadequate. We recommend Full Funding if possible to avoid deferred maintenance or special assessments. Baseline Funding maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk.

CREDENTIALS

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including CDD communities, Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums and commercial investment properties.

Personal Service is our common business practice but our attention to detail, quick response and interest in client relationships continues to earn us a larger market share of work each year.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining District value.

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

DEFINITIONS

Adjustment to Useful Life: Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

Cash Flow Method: A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

Component Method: A funding method that fully funds each reserve component then sums those for the annual contribution.

Current Funding Plan: The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

Effective Age: Difference of useful and remaining useful life.

Fully Funded Balance: Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

Interest Contribution: The interest that should be earned on invested reserves.

Percent Funded: Ratio of reserve balance to fully funded balance.

Remaining Life: Number of years a component is projected to continue to function.

Threshold Funding: This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

Useful Life: The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history.